

# EPA Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency  
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

OH #444 810605 OHS-000-001-153

**A Person Required to Notify:**

Enter the name and address of the person or organization required to notify.

Name General Electric Co., Electromaterials Business Dept.  
Street 1350 South Second Street  
City Coshocton State Ohio Zip Code 43812

**B Site Location:**

Enter the common name (if known) and actual location of the site.

Name of Site General Electric Co., Coshocton Plant  
Street 1350 South Second Street  
City Coshocton County Coshocton State Ohio Zip Code 43812

**C Person to Contact:**

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Larsen, Vernon - Mgr, Environmental Engineering  
Phone (614) 622-5310 Ext 328

**D Dates of Waste Handling:**

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1947 To (Year) 1976

**E Waste Type: Choose the option you prefer to complete**

**Option 1:** Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

**General Type of Waste:**  
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☒ Organics
- 2. ☒ Inorganics
- 3. ☒ Solvents
- 4. ☐ Pesticides
- 5. ☒ Heavy metals
- 6. ☒ Acids
- 7. ☒ Bases
- 8. ☒ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify)

**Source of Waste:**  
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☒ Other (Specify)

**Option 2:** This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

**Specific Type of Waste:**

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.


EPA Region 5 Records Ctr.



364645

000011 JUN 15 81

RECEIVED  
JUN 5 1981

400

Synthetic resin mfr  
Plastics manufacture

JUN 15 1981

## Notification of Hazardous Waste Site

## Side Two

**F Waste Quantity:**

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

**Facility Type**

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☒ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) \_\_\_\_\_

**Total Facility Waste Amount**

cubic feet

~~220 000~~

gallons

~~29 410~~ 1,675,230**Total Facility Area**

square feet

~~110 000~~

acres

~~2.5~~**G Known, Suspected or Likely Releases to the Environment:**

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☒ Known ☐ Suspected ☐ Likely ☐ None

**Note:** Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

**H Sketch Map of Site Location: (Optional)**

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Sketch map attached, responsive also to Description of Site in Item I.

**I Description of Site: (Optional)**

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

There are two abandoned disposal facilities at this plant site. One, with an estimated area of 96 000 sq ft, was a landfill in which waste materials from the manufacture of synthetic resins and laminated plastics made from them were buried during the period from 1947 until the landfill was graded, covered, levelled, and put to grass in 1968.

The other facility was a lagoon or earth impoundment with an estimated area of 14 000 sq ft, constructed under permit from the Ohio Department of Health in 1954 to receive process water, containing about 6% phenol, from the synthetic resin plant. This water percolated into the ground where the phenol was destroyed by bacterial action. This lagoon was filled in, levelled, and put to grass in 1976 upon installation of an NPDES-permitted wastewater pretreatment process.

The attached sketch map of the neighborhood of the plant site shows the locations of the lagoon and the landfill, and other features required for the description of the site.

**J Signature and Title:**

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name General Electric Co.

Street 1350 South Second Street

City Coshocton State Ohio Zip Code 43812

Signature

*L. L. Larrow*

Date May 12, 1981

- ☒ Owner, Present  
☐ Owner, Past  
☐ Transporter  
☐ Operator, Present  
☐ Operator, Past  
☐ Other